

## Firmware update

### STS 1932 IPM

Update to Version  $\geq 21.0$

02/18

#### Warning:

When updating to version 20.0, the system platform (the operating system) of the device was also updated.

For updates of devices with firmware versions  $\leq 19.x$  to firmware versions  $\geq 21.0$ , **first the corresponding firmware version 20.0 must be mandatory installed** in order to update the system platform.

To our regret, version 20.0 unfortunately has a bug that needs to be fixed before updating to versions  $\geq 21.0$ .

**After the update to version 20.0 you must update to version "20.0uploadfix". As of version "20.0uploadfix", updates to versions  $\geq 21.0$  are possible.**

We ask you to excuse this inconvenience.

**Update requirements for the firmware versions  $\geq 21.0$  is the respective firmware version "20.0uploadfix"!**

$\leq V19.x \rightarrow V20.0 \rightarrow$  "20.0uploadfix"  $\rightarrow \geq 21.0$



During the update do NOT disconnect the device from the power supply! Disconnecting from the power supply will damage the device. Wait until the update is completed.

GSS Grundig Systems GmbH • Beuthener Straße 43 • D-90471 Nuremberg  
Phone: +49 (0) 911 / 703 8877 • Fax: +49 (0) 911 / 703 9210  
[www.gss.de/en](http://www.gss.de/en) • [info@gss.de](mailto:info@gss.de)

Service: Phone: +49 (0) 911/703 2221; Fax: +49 (0) 911/703 2326; [service@gss.de](mailto:service@gss.de)